

## Release note

### Payload Firmware Update

The payload firmware update is now ready for download.

The firmware update includes the following:

---

#### 2.2.1-1

- This release supports following payloads:
  - EasyOneLiDARUHR, EasyOneLiDARUHR Lite, EasyOneLiDARUHR+.
- Camera fix: Removed limit for minimal trigger interval. All camera events will now be captured and geotagged.

---

#### 2.2.0-21

- This release supports following payloads:
  - EasyOneLiDARUHR, EasyOneLiDARUHR Lite, EasyOneLiDARUHR+.
- WebUI:
  - Added Settings profile selection and Pilot Logbook.
  - Added heartbeat and recording indicator in WebUI.
  - Added progress bar for pre-flight data transfer.
  - Added settings option to set camera picture interval.
- Other Changes and Fixes:
  - Added direct access to internal memory through FTP protocol.
  - APX T04 logging will be programmatically set to "Always" mode.
  - Oversized UDF Frame will be split into smaller frames.
  - Increased GNSS fix quality to improve home position for proximity mode.
  - Geotagging fix: Pictures will be tagged after flight in case of a late APX event.
  - Check full External USB Drive in flight and prior to flight.

---

#### 2.1.0

- Initial release for following payloads:
  - EasyOneLiDARUHR, EasyOneLiDARUHR Lite, EasyOneLiDARUHR+.
- Introduced WebUI:
  - User interface available through Wi-Fi as a web page running on the payload internal server.
  - This interface provides status overview of the system, troubleshooting information and configuration parameters.

